

Case No.	Respondent	Summary of Findings	Summary of Board Action
OCTOBER 23, 2007			
M07-072	Timothy M. O'Neill Land Surveyor #17403	On or about May 2004 and October 2006, Respondent prepared and sealed ALTA/ACSM surveys for the Tucson International Gateway Center and failed to record a Results of Survey with the Pima County Recorder's Office in the required time.	Letter of Reprimand Probation – Respondent's Land Surveyor Registration No. 17403 shall be placed on probation until Respondent records a Results of Survey of Lots 11-14 of the Tucson International Gateway Center with the Pima County Recorder's Office. Cost of Investigation – Pay cost of investigation in the amount of \$160.00.
M08-042	O'Neill Engineering, Inc.	On or about September 2004 through March 4, 2007, Respondent Firm provided engineering and land surveying services in the State of Arizona without registration.	Administrative Penalty – Pay an administrative penalty of \$1,000.00. Cost of Investigation – Pay cost of investigation in the amount of \$75.00.
M07-120	Innovative Earthworks, Inc.	On or about June 2006 through July 30, 2007, Respondent Firm provided engineering services in the State of Arizona without registration.	Administrative Penalty – Pay an administrative penalty of \$500.00. Cost of Investigation – Pay cost of investigation in the amount of \$75.00.
M07-074	William J. Christenson P.E. (Structural) #34626	On or about June 2005, Respondent conducted a site inspection and prepared a report of the structural inspection of the residence foundation walls. Respondent failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent's June 2005 Report was deficient in that Respondent failed to indicate that the lateral walls are not supported at the top; that perpendicular blocking was not used; and that the walls were not evaluated as cantilevered walls. Respondent failed to use lateral earth loads in his calculations of the walls; failed to verify the rebar sizes and location of the rebar in the walls; and failed to determine the correct water source as it relates to the walls in that the water is not being directed away from the foundation walls.	Letter of Reprimand Peer Review – Peer review of Respondent's next three (3) structural projects having basements. Cost of Investigation – Pay cost of investigation in the amount of \$675.00.
M06-160	Terry L. Moore P.E. (Civil) #09293	On or about August 4, 2005, Respondent sealed an Engineer's Certificate of Completion, knowing that it was not correct at the time he sealed it, and failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time.	Letter of Reprimand Cost of Investigation – Pay cost of investigation in the amount of \$235.00.

M05-308 M05-326 M06-157 M06-175 M06-214 M06-274 M06-284 M06-285 M07-033 M07-035 M07-057 M07-075 M07-109	Thomas H. Trimble P.E. (Civil) #15620 Land Surveyor #15343	<p>Respondent failed to apply the technical knowledge and skill which would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared engineering plans and surveys that were incomplete and/or contained errors; failed to complete the engineering and land surveying services; and failed to provide clients with plans.</p> <p>On or about May 18, 2006, after receiving payment from his client, Respondent failed to pay a collaborating registered professional in the required time.</p>	<p>Suspension – Respondent’s Arizona Registered P.E. (Civil) No. 15620 registration and Arizona Registered Land Surveyor No. 15343 registration shall be suspended for a period of one (1) year.</p> <p>Probation – Respondent’s Professional Engineer (Civil) Registration No. 15620 and Land Surveyor Registration No. 15343 shall be placed on probation for two (2) years following the one (1) year suspension. The terms and conditions of probation are as follows:</p> <p>a. Administrative Penalty – Pay an administrative penalty of \$5,000.00.</p> <p>b. Peer Review – Following Respondent’s one (1) year suspension, Respondent shall submit all engineering and surveying projects to a peer reviewer for a twelve (12) month period.</p> <p>Cost of Investigation – Pay cost of investigation in the amount of \$2,240.00.</p>
---------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------